Index

ABS (acrylo–butadiene–styrene), 250
Acetal resins, 250
Addition polymerisation, 245
Adhesives, 353, 356
Age-hardening, 235
Ageing of plastics, 332
Air-hardening steels, 206, 209
Allotropy, 44–45, 136
Alloy cast irons, 222
Alloys, 118–134
Alloy steels, 202–216; elements in, 207
Aluminium alloys, 231–236; precipitation hardening of, 234
Aluminium bronze, 230
Amorphous: solids, 54; state, 46, 50
Anisotropy, 287
Annealing, 89; of steel castings, 182; process-, 181; spheroidising-, 181
Anode, 315
Antimony, in bearing metals, 241
Arc-welding processes, 358–360
Atom, 2
Atomic: bomb, 397; mass number, 11, 389; nucleus, 9; pile, 398; structure, 4–17; weight, 11
Austempering, 199
Austenite, 173; transformations, 174–178, 181–199
Austenitic: cast irons, 219; steels, 203, 214

Bainite, 188–190
Bakelite, 244, 256
Ball-bearing steels, 210
Bearing: bronzes, 242; metals, 240–242; plastics, 305; sintered alloys, 242
Beryllium, 299; bronze, 230; oxide, 279, 280
Binary alloys, 119
Bismuth–cadmium alloys, 155
Blow moulding, 106
Body-centred cubic, 44
Borides, 303
Boron, 299; carbide, 279, 300; in glass, 282
Bragg's Law, 39
Brass, 224–227; compositions of, 232; free-cutting, 224; high-tensile, 232
Bravais lattice, 35–36
Brazing, 357; solders, 357
'Brightray', 238
Brinell test, 65
Brittle fracture, 335, 340
Bronze: aluminium bronze, 230; phosphor bronze, 230; tin bronze, 224, 228–232
Bronze welding, 358
Butt welding, 361

Calendering, 107
Carbides, 303; stability of, 204
Carbon, 20; compounds, 20–25; fibres, 287–289
Case-hardening of steel, 200
Casein plastics, 256
Casting: die-, 100; ingot-, 95; investment-, 99; of ceramics, 101; of plastics, 101; processes, 95–102; sand-, 98; shell-mould-, 98
Cast iron, 216–222; alloy, 222; compositions of, 219; malleable, 221, 222; microstructures of, 218–221; properties of, 218, 219; spheroidal-graphite, 218; varieties and uses of, 219; welding of, 365
Cast structures, 50, 416
Cathode, 315
Cellulose, 296; acetate, 251; acetyl/butyrate, 251; nitrate, 251
Cement, 305
Cemented carbides, 301, 303
Cementite, 173
Ceramics, 273–281; corrosion of, 333; electrical properties, 281; hardness, 279; melting points, 280; strength, 279; structures, 274–278
Cermets, 297, 301, 303
CFRP, 300
Charpy test, 66–68
Chill crystals, 50, 51
'Chromidium', 219
Chromium: in cast iron, 219, 222; in steels, 171, 213–215
Cleavage planes, 71
Close-packed hexagonal, 41–43
Cobalt: in high-speed steels, 211; in magnets, 380, 381
Coercive force, 379
Coherent precipitation, 129, 235
Coinage alloys, 232
Coining, 110
Cold: forging, 110; rolling, 108; welding, 362; working, 71, 108
Cold-setting plastics, 255
Composite: bearings, 304; materials, 296–309
Compression moulding, 116
Concrete, 306; pre-stressed, 308; reinforced, 307
Condensation polymerisation, 254
Conductivity, electrical, 368–376; of aluminium, 231; of copper, 223
Constructional steels, 206, 209
Co-polymer, 248
Copper, 223; alloys of, 149, 159, 224–231; conductivity of, 223; in cast irons, 222; in white metals, 242
Coring, 123, 153
'Corronel', 238
Corrosion, 310–330; crevice-, 327–328; dry-, 310; electrolytic (galvanic), 312; protection from, 329–330; -resistance, 206; sacrificial, 321
Cottrell atmospheres, 127

Coulomb: force, 33; Law, 13
Covalent bond, 18–20
Cracks: detection of, 404–407; formation of, 338
Creep, 341–346; in metals, 341; in plastics, 269; -resistance, 345; -stress, 343
Crevice corrosion, 327–328
Critical: cooling rate, 193; mass, 397
Cross-linking, 254
Crystal: boundaries, 84; imperfections, 74; structure, 32, 41
Crystallisation: of metals, 45–51; of polymers, 259
Crystallites, 259
Cupro-nickel, 230

Deep-drawing, 109
Deformation, 69–93; of polymers, 91
Degree of freedom, 142
Dendrite, 48; dendritic growth, 48
Depth of hardening, 194, 195
Devitrification, 282
Diamond, structure of, 52
Diamond pyramid hardness, 65
Die-casting, 100; alloys, 237, 240
Dies, steels for, 210
Diffusion, 125–127
Dipole, 26; moments, 26
Dislocation, 75, 339; climb, 87; edge-, 76; jog, 88; screw-, 78; theory, 76–88
Dispersion: forces, 27; hardening, 298, 302
Drawing processes, 108
Drop forging, 102
Dry corrosion, 310
Ductile fracture, 335
Ductility, 56, 61
Duralumin, 234, 237
Dynamic testing, 414

Einstein's Equation, 15, 395
Elastic: deformation, 58, 69; limit, 63; modulus, *see* Young's Modulus
Elastomer, 289
Electrical: conductivity, 366, 368; properties, 41, 366; resistance, 238, 367
Electric-arc welding, 358–359
Electrochemical series, 313
Electrode potential, 313
Electrolyte, 316
Electrolytic corrosion, 312–330
Electron, 2; beam welding, 360; 'cloud', 70, 366; compounds, 133; microscope, 430; shells, 8; spins, 7
Electro-slag welding, 359
Electrovalent bond, 18, 30–33
Elongation, per cent, 61
Embossing, 111
Endurance limit, 347
'Energy gap', 368
'Engineering stress', 63
Epoxy resins, 257
Equi-axed crystals, 50, 51
Equilibrium diagrams, 145–171; construction of, 149
Erichsen test, 68

Etching: macrosections, 105; microsections, 422
Eutectic, 119, 154–159; point, 154, 158
Eutectoid, 159; point, 205
Expanded plastics, 271
Explosion: forming, 113; welding, 363
Extrusion, 105, 115; impact-, 110

Face-centred cubic, 43–44
Fatigue, 346–349; fracture, 348; limit, 347
Ferrite, 173
Ferromagnetism, 377
Fibre, 103–105; carbon-, 287–289, 299; materials, 299; reinforced plastics, 298–301
Fick's Laws, 125, 152
Fictive temperature, 281
Fillers, 270
Flame hardening, 201
Flash welding, 362
Flow lines, 103–105
Fluorescent tests, 405
Foamed plastics, 271
Forging, 102; drop-, 102
Fracture, 335–341
Frank-Reed source, 80
Free-cutting brass, 224
Friction welding, 362
Furnaces, melting, 95, 96
Fusion welding, 358–360

Galvanic: corrosion, 313–322; protection, 330
Gamma (γ) radiography, 410
Gas-shielded arc welding, 359
Gas welding, 358
Gauge length (tensile test pieces), 61
Germanium, 368
Giant molecules, 52
Glass, 281–287; fibre, 285; heat-treatment of, 286; mechanical properties of, 284; reinforced composites, 282, 299; transition temperature, 261, 281
Glues, 356
Grain: boundaries, 50; growth, 90, 204; refinement, 205, 207; size, 90
Graphite, 53, 173
Griffith's Crack Theory, 337
GRP, 282, 299, 300
Gunmetal, 230, 232
Gutta-percha, 291

Hardenability, 194
Hardening: flame-, 201; induction-, 201; of steel, 196; surface-, 199
Hardness, 64; measurement of, 64–66
'Hastelloy', 238
Heat-resisting: alloys, 216, 238; steels, 216, 312
Heat-treatment: of aluminium alloys, 234; of steels, 181–199, 212
Hexagonal close-packed, *see* Close-packed hexagonal
High-speed steels, 211; hardening of, 212
High-temperature alloys, 214, 216, 238
Homologous series, 23
Hooke's Law, 58

Hot: pressing, 102; rolling, 105; working processes, 102–107
Hume-Rothery, 122
Hydrogen: bomb, 401; bond (bridge), 28
Hyper-, hypo-eutectoid, 177

Impact tests, 66–68
Induction: hardening, 201; welding, 362
Ingot: casting, 95; structures, 50
Inhibitors, 325
Injection moulding, 116
Inspection of welds, 403
Insulators (electrical), 372
Intermediate phases, 131–134, 167–168
Intermetallic compounds, 132, 167
Internal defects, detection of, 408–414
Interstitial: compounds, 134; solid solutions, 121
Iron, 136, 172; -carbon diagram, 174
Isomerism, 23
Isothermal: transformations, 190; treatments, 198
Isotopes, 11, 12, 391, 394, 396, 399
Izod test, 66–68

Jominy test, 194–195

Kinetic Theory of Matter, 45

Laminates, 258
Laser welding, 360
Lattice, 33–35
Laves phases, 132
Layer structures, 53
Lead: alloys of, 166; in brass, 224
Lever Rule, 147
Lignin, 296
Limiting creep stress, 343
Limit of proportionality, 63
Liquidus, 150
Lost-wax process, *see* Casting, investment
Lower critical temperature, 175

Machinability, 181, 224
Magnesium: alloys of, 167, 236; oxide, 274
Magnetic: domains, 378; dust tests, 406; hysteresis, 379; permeability, 382
Magnetism, 376–382
Malleability, 56, 60
Malleable cast irons, 222
Manageing steels, 208
Marsh machine, 81
Martempering, 198
Martensite, 185, 187
'Mass defect', 15
Mass effect (of heat treatment), 194
'Mazak', 240
Mechanical: properties, 56–67; testing, 56–67
Melamine formaldehyde, 256
Melting point (of polymers), 260
Mer, 245
Metallic-arc welding, 359
Metallic bond, 40–41, 366–368
Methane, 21
Micelles, 54
Microscope, 426; care of, 430; electron-, 430; magnification, 427; objectives, 427
Microsections: etching of, 422; preparation of, 420; selection of, 419
MIG process, 359
Miller indices, 36–38
Miscibility, 120
'Modification' (of aluminium–silicon alloys), 231
Modulus, Young's, 58
Moh's Scale, 64
Molecule, 18–29
Molecular crystals, 54
Molybdenum: boride, 303; in high-speed steels, 211, 212; in steels, 204, 207, 208, 209
Monel Metal, 232
Monomer, 245
Mortar, 306

Nailing, 350
Neutron, 3, 12, 331
Nickel: alloys of, 168, 238, 240; in aluminium alloys, 237; in cast irons, 222; in steels, 202–206; 'silvers', 230
'Nimonic' alloys, 238
Niobium, in steels, 204, 213
'Ni-resist', 219
Nitriding, 200; advantages of, 200; steels, 200
Noble gases, 19
Nodular cast iron, *see* Spheroidal-graphite cast iron
Non-coherent precipitates, 131
Non-destructive testing, 403–417; applications, 416
Normalising, 182
Novolak, 254
Nuclear: binding force, 12; binding energy, 15; energy, 15, 395, 398; fission, 16, 395–400; fusion, 401; reactions, 392–400; stability, 386
Nucleon, 13, 386
Nylon, 250

Objectives, microscope, 427
Oil-less bearings, 115, 135
Oil-quenching, 193
Orbital, atomic, 6
Oxidation, 311
Oxy-acetylene welding, 358

Partial solid solubility, 159–163
Particle: hardening, 298; hardened composites, 301
Pauli's Exclusion Principle, 7, 8, 366
Pearlite, 177
Penetrant tests, 404
Periodic Classification (Table), 7, 10, 18
Peritectic reactions, 163–166
Permanent magnet alloys, 380
Permeability (μ), 382
'Perspex', 250
Phase: definition of, 119, 136; diagrams, 141–171; equilibrium, 136–171; Rule, 142
Phenol formaldehyde, 254, 256, 356
Phosphor bronze, 230, 232

Pipe, in ingots, 97
Planck's Constant, 6
Plasma-arc welding, 360
Plastic deformation (strain), 60, 70, 71–87
Plastics, 244–272; foams, 271; properties of, 259–269; shaping of, 106–107, 115–117; structures and compositions of, 247, 249–253, 256, 259
Plasticisers, 270
Platinum–silver alloys, 163
Plutonium, 400
Poisson's Ratio, 293
Polar bonds, 33
Polyamides, 250
Polyesters, 250, 257
Polyethylene, 24, 245, 247, 249
Polyethylene terephthalate, 250
Polyisoprene, 292
Polymerisation, 245
Polymers, 244–272; mechanical properties of, 263
Polymethyl methacrylate (PMM), 247, 250
Polymorphism, 45, 172
Polypropylene, 249
Polystyrene, 247, 249
Polytetrafluoroethylene (PTFE), 247, 250
Polythene, 24, 245, 247, 249
Polyurethanes, 251, 257
Polyvinyl: acetate, 247, 249; chloride, 247, 249
Polyvinylidene chloride, 247, 250
Portevin's Rules, 147
Portland cement, 306
Pourbaix diagrams, 323
Powder metallurgy, 114, 134
Precipitation: from a solid solution, 129; hardening, 123, 208, 230, 234, 236, 237, 238
Pressing, 102, 111
Pressure: die-casting, 100; welding, 360–363
Process annealing, 181
Projection welding, 361
Proof stress, 63
Protection of metallic surfaces, 320
Proton, 3
Pseudo-binary diagram, 171
PTFE, *see* Polytetrafluoroethylene

Quantum shells, 7
Quench cracks, 193
Quenching of: aluminium alloys, 235; steels, 179, 193, 196, 210–211, 213

Radiation: alpha (α)-, 384; beta (β)-, 384; gamma (γ)-, 385; damage, 331–332; detection of, 386
Radioactive: decay, 389; series, 388, 391
Radioactivity, 383; artificial-, 393
Radiography, 408–413
Recrystallisation, 89; temperature, 89
Reduction: chemical, 311; in area, 62
Relative atomic mass, *see* Atomic mass
Relief of stress, 87, 89
Remanence, 379
Resistance alloys, 238
Resolving power (of lenses), 428
Riveted joints, design of, 350
Riser, 98
Rockwell Hardness, 66
Rolling, 105, 108; mills, 105, 108
Rubber pressing, 111
Rubbers, 289–295; mechanical properties of, 293; structures of, 290; synthetic, 293
Ruling section, 194
Runner, 98

Sacrificial corrosion, 321
Sand casting, 98
Scission, 332
Screws, 350; steel for, 180
Seam-welding, 361
Season cracking, 326
Secondary: hardening, 213; solid solutions, 132
Segregation: major, 97; minor, 97
Semi-conductors, 368, 372–376
Shell-moulding, 98
Shrinkage cavities, 49
Side branching, 255
Silicates, 275–280
Silicon, 368; in cast iron, 216–218
Silicon–aluminium alloys, 231
Silicon carbide, 279, 300
Silicones, 257
Silver: alloys of, 159, 163; solders, 357
Sintered: aluminium powder (SAP), 302, 304; bearings, 114, 242, 305; carbides, 301, 303
Sintering, 114
Size factor, 132
Slip, 69; bands, 71, 72; planes, 70
Sodium: chloride, 33; in 'modification', 231
Soldering, 355
Solders, 357; silver-, 357
Solid solutions, 119–131, 149–154; diffusion in, 125, 153
Solidus, 150
Solute, 119; 'atmospheres', 127
Solution, 118–131; treatment of aluminium alloys, 234
Solvent, 119
Solvus, 160
Sorbite, 197
Space lattice, 33–35
Specific: modulus of elasticity, 60, 287; strength, 288
Spheroidal-graphite cast iron, 218
Spheroidising, 181
Spinning, 112
Spot-welding, 361
Stainless: iron, 214; steels, 213–215, 329
Steel: compositions, 172, 178–181; heat-treatments of, 181–201; ingots, 95; properties and uses of, 178–181; structures of, 173–189
Stereoisomerism, 290
Strain, definition of, 57
Stress: corrosion, 325; definition of, 57; 'engineering-', 63; relief, 87
Stress–strain diagrams: 62; of plastics, 267
Stretch forming, 112
Structural steels, 179, 180
Sub-critical annealing, 181

Submerged-arc welding, 359
Substitutional solid solutions, 121
Superconductivity, 370–372
Surface defects, detection of, 403–407
Surface hardening of steels, 199

Tantalum, 168; carbide, 280
Tarmacadam, 309
Temper brittleness, 206
Tempering of steels, 196
Tensile: strength, 63; tests, 61
Ternary equilibrium diagrams, 168–170
Test-pieces, 61; proportional, 61
Thermal equilibrium diagrams, *see* Equilibrium diagrams
Thermit welding, 360
Thermodynamics, 136
Thermoplastic polymers, 246
Thermosetting polymers, 248, 254
Thorium, 388; oxide, 280
TIG process, 359
Time/yield stress, 344
Tin: in bearing metals, 240; in brass, 224; in bronze, 224; in solders, 357
Titanium, 242; alloys, 242; carbide, 303; in steels, 204, 205, 213
Tool steels, 180, 208, 210
Toughness, 66
Tough-pitch copper, 223
Transfer moulding, 116
Transformation rates, retardation of, 193, 205
Transition temperature, 341
Troostite, 197
TTT curves, 188–198
Tungsten: carbide, 303; in steels, 211, 212
Twins: annealing, 86; deformation, 85

Ultimate tensile stress, *see* Tensile strength
Ultrasonic: testing, 413; welding, 263
Upper critical temperature, 175

Uranium, 388, 396–400
Urea–formaldehyde, 256

Vacancies (vacant sites), 74
Vacuum forming, 107
Valency (valance): band, 368; compounds, 132
Vanadium: in cast iron, 222; in steels, 204, 207, 211
Van der Waals forces, 25, 53, 246, 259, 276
Vickers Diamond Pyramid Hardness, 65
Vinyl plastics, 246–248
Viscoelasticity, 92, 264–266
Visual inspection, 403
Vulcanisation, 291, 292

Weld: decay, 213, 329, 364; inspection, 403, 417
Welding: processes, 357–363; structures, 363–365
Welding of: alloy steels, 364; aluminium alloys, 365; carbon steels, 364; cast iron, 365; magnesium alloys, 365; plastics, 362; refractory metals, 360; stainless steels, 364
'Whiskers', 81, 300
'White' bearing metals, 240–242
Widmanstätten structure, 182
Wöhler fatigue test, 346
Wood, 296; structure of, 296
Work-hardening, 86

X-ray analysis, 38–40, 55
X-radiography, 408

Y-alloy, 236
Yield strength, 63
Young's Modulus of Elasticity, 58

Zener voltage, 376
Zinc: alloys, 240; in bronze, 230, 232; in magnesium alloys, 236, 239; protective coating of, 320; sacrificial protection by, 321, 330
Zirconium: in magnesium alloys, 239; oxide, 280